

SAFETY DATA SHEET

Section 1. Identification of the material and the supplier

Product: Liquid Glass Base

 Item Code:
 1261

 UN No.
 3082

Product Use: Resin for lamination when used with liquid glass hardener

Restriction of Use: Refer to Section 15

Australian Manufacturer: **Norglass Paints**Address: 59 Moxon Road

Punchbowl NSW 2196

Australia

Telephone: +61 2 9708 2200 Email: info@norglass.com.au

New Zealand Supplier: xxx Address: xxx

XXX

Telephone: 0508 724687

Emergency Numbers:

Australia: 13 1126

New Zealand: 0800 764 766 (National Poison Centre)

Date of SDS Preparation: 7 November 2016 v2

Section 2. Hazards Identification

This substance is hazardous according to:

New Zealand - The HSNO (Minimum Degrees of Hazard) Regulations 2001 Australia - Approved Criteria for Classifying Hazardous Substances

[NOHSC:1008(2004)]

New Zealand:

EPA Approval No: Surface Coatings and Colourants (subsidiary) - HSR002670

Pictograms







Irritant

Chronic

Ecotoxic

Signal Word: **DANGER**

HSNO Classification	Hazard Code	Hazard Statement	GHS Category
6.3A	H315	Causes skin irritation.	Category 2
6.4A	H319	Causes serious eye irritation.	Category 2A
6.5B	H317	May cause an allergic skin reaction.	Category 1

Product Name: Liquid Glass Base
Date of SDS: 7 November 2016
Issued by: Technical Compliance Consultants (NZ) Ltd
Tel: 64 9 475 5240 www.techcomp.co.nz

6.9A	H372	Causes damage to organs through	Category 1
		prolonged or repeated exposure.	
9.1B (NZ only)	H411	Toxic to aquatic life with long lasting effects.	Category 2

Prevention Code	Prevention Statement
P103	Read label before use.
P260	Do not breathe fumes, gas, mist or vapours.
P264	Wash hands thoroughly after handling.
P270	Do not eat, drink or smoke when using this product.
P272	Contaminated work clothing should not be allowed out of the workplace.
P273	Avoid release to the environment.
P280	Wear protective clothing.

Response Code	Response Statement
P314	Get medical advice/attention if you feel unwell.
P362	Take off contaminated clothing and wash before re-use.
P391	Collect spillage.
P302 + P352	IF ON SKIN: Wash with plenty of soap and water.
P305 +	IF IN EYES: Rinse cautiously with water for several minutes. Remove
P351+P338	contact lenses, if present and easy to do. Continue rinsing.
P333 + P313	If skin irritation or rash occurs: Get medical advice/ attention.
P337 + P313	If eye irritation persists: Get medical advice/attention.

Storage Code	Storage Statement
None allocated	

Disposal Code	Disposal Statement
P501	Dispose of according to Local Regulations or Authorities

Section 3. Composition / Information on Ingredients

Ingredients	Wt%	CAS NUMBER.	
Low viscosity Epoxy resin	100%	25068-38-6	

Section 4. First Aid Measures

Routes of Exposure:

If in Eyes Rinse cautiously with water for several minutes. Remove contact lenses, if

present and easy to do. Get immediate medical attention.

If on Skin Wash with plenty of soap and water. Take off contaminated clothing and

wash before re-use. If skin irritation or rash occurs: get medical

advice/attention.

If Swallowed Rinse mouth. If the victim is conscious give water or milk to drink to dilute

the effect. If vomiting occurs, place victim face downwards, with the head turned to the side and lower than the hips to prevent vomit entering the

lungs. Seek medical attention if you feel unwell.

If Inhaled Remove person to fresh air. Remove contaminated clothing and loosen

remaining clothing. Allow person to assume most comfortable position and keep warm. Keep at rest until fully recovered. Get medical advice if

breathing becomes difficult or if you feel unwell.

Section 5. Fire Fighting Measures

Hazard Type	Non Flammable
Hazards from combustion products	Hazardous combustion products:- Carbon monoxide, carbon dioxide- toxic gases of combustion will not decompose with explosion.
Suitable Extinguishing media	Use water mist, foam, carbon dioxide or dry chemicals as extinguishing media
Precautions for firefighters and special protective clothing	Wear full body protection and self-contained breathing apparatus.
HAZCHEM CODE	3Z

Section 6. Accidental Release Measures

Wear protective equipment as detailed in Section 8. Clear area of any unprotected personnel.

Extinguish all sources of ignition. Spilt material should be absorbed into dry inert material such as sand, earth or sawdust and disposed by incineration by approved agent or local regulations. Adequate steps should be taken to prevent spillage reaching waterways and drains.

Section 7. Handling and Storage

Precautions for Handling:

- Read label before use.
- Do not handle until all safety precautions have been read and understood.
- Keep container tightly closed.
- Do not breathe fumes, gas, mist or vapours.
- Wash hands thoroughly after handling.
- Do not eat, drink or smoke when using this product.
- Wear protective clothing.

Precautions for Storage:

- Store away from incompatible materials listed in Section 10.
- Keep cool and container closed.

Section 8	Exposure Controls / Personal Protection	
-----------	---	--

WORKPLACE EXPOSURE STANDARDS (provided for guidance only)

TWA STEL Substance ppm mg/m³ ppm mg/m³

Not ingredients have exposure limits.

Workplace Exposure Standard – Time Weighted Average (WES-TWA). The time-weighted average exposure standard designed to protect the worker from the effects of long-term exposure. Workplace Exposure Standard – Short-Term Exposure Limit (WESSTEL). The 15-minute average exposure standard. Applies to any 15- Minute period in the working day and is designed to protect the worker against adverse effects of irritation, chronic or irreversible tissue change, or narcosis that may increase the likelihood of accidents. The WES-STEL is not an alternative to the WES-TWA; both the short-term and time-weighted average exposures apply.

Engineering Controls

Use only in well ventilated areas. Introduce local exhaust ventilation were necessary.

Personal Protection

Eyes	Wear safety goggles with side shields.		
Hands and	Wear chemical resistant gloves. Wear overalls and use barrier cream.		
Skin			

Respiratory	Avoid breathing vapour of dust by wearing AS1716 approved respirators.
Respiratory	Avoid breathing vapour of dust by wearing AS1716

Section 9 Physical and Chemical Properties

Appearance	Clear/pale yellow low viscosity liquid with a mild odour.
Odour	Mild odour
Odour Threshold	Not applicable
pH	Not applicable
Boiling Point	Not measured
Melting Point	Not applicable
Freezing Point	Not applicable
Flash Point	>155°C
Flammability	Not applicable
Upper and Lower	Not applicable
Exposure Limits	
Volatile Component	Not applicable
Vapour Density	Not applicable
Specific Gravity	1.09
Solubilities	Insoluble
Partition Coefficient:	Not applicable
Auto-ignition	Not applicable
Temperature	
Decomposition	Not applicable
Temperature	
Kinematic Viscosity	Not applicable
Particle Characteristics	Not applicable

Section 10. Stability and Reactivity

Stability of Substance	This product is stable under normal conditions.
Conditions to Avoid	Avoid excess heating.
Incompatible Materials	Avoid contact with bases acids amines and oxidising agents.
Hazardous Decomposition	Hazardous polymerisation will not occur by itself, but
Products	irreversible polymerization will occur with amines resulting in considerable heat. Hazardous combustion products:- Carbon monoxide, carbon dioxide- toxic gases of combustion will not decompose with explosion. Dust created be sanding of cured products may cause a dust explosion hazard. Dust generated should be removed by vacuum.

Section 11 Toxicological Information

Acute Effects:

Swallowed	Not applicable
Dermal	Not applicable
Inhalation	Not applicable
Eye	Causes severe eye irritation.
Skin	Causes skin irritation. May cause an allergic reaction.

Chronic Effects:

Carcinogenicity	Not applicable
Reproductive	Not applicable.
Toxicity	
Germ Cell	Not applicable.
Mutagenicity	
Aspiration	Not applicable.
STOT/SE	Causes damage to organs through prolonged or repeated exposure.

STOT/RE Not applicable.

Section 12. Ecotoxicological Information

New Zealand:

HSNO Classes: 9.1B = Toxic to aquatic life with long lasting effects.

Persistence and degradability	No data available
Bioaccumulation	No data available
Mobility in Soil	No data available
Other adverse effects	No data available

Do not allow to enter waterways.

Section 13. Disposal Considerations

Disposal Method: Place recovered product into an appropriate waste container for disposal

through appropriate waste company or specialized landfill in accordance

with local regulations.

Precautions: Ensure waste container containing recovered product is labelled "Hazardous

Waste - "Ecotoxic". If triple rinsing container, add rinsate to waste container for

disposal.

Disposal methods to avoid: Do not allow to enter waterways.

Section 14 Transport Information

This product is classified as a Dangerous Good for transport in NZ; NZS 5433:2012 and Australian Dangerous Goods Code ADG7 and NOHSC:1008(2004)

Road and Rail Transport

UN No: 3082 Class-primary 9 Packing Group II

Proper Shipping Name: ENVIRONMENTALLY HAZARDOUS LIQUID, N.O.S

Air Transport

UN No: 3082 Class-primary 9 Packing Group II

Proper Shipping Name: ENVIRONMENTALLY HAZARDOUS LIQUID, N.O.S

Marine Transport

UN No: 3082 Class-primary 9 Packing Group II

Proper Shipping Name: ENVIRONMENTALLY HAZARDOUS LIQUID, N.O.S

Section 15 Regulatory Information

This substance is hazardous according to:

New Zealand - The HSNO (Minimum Degrees of Hazard) Regulations 2001 Australia - Approved Criteria for Classifying Hazardous Substances

[NOHSC:1008(2004)] Poison Schedule: Not Scheduled

New Zealand:

EPA Approval Code: Surface Coatings and Colourants (subsidiary) - HSR002670

HSNO Classification: 6.3A, 6.4A, 6.5B, 6.9A, 9.1B

HSNO Controls:

Trigger quantities for this substance:

	Trigger Quantity	
Approved Handler	Not required	
Location Certificate	Not required	
Tracking Trigger Quantities	Not required	
Signage Trigger Quantities	1000L	
Emergency Response Plan	1000L	
Secondary Containment	1000L	
Restriction of Use	None	

Section 16	Other Information
Glossary	
EC50	Median effective concentration.
EEL	Environmental Exposure Limit.
EPA	Environmental Protection Authority
HSNO	Hazardous Substances and New Organisms.
LC50	Lethal concentration that will kill 50% of the test organisms
	inhaling or ingesting it.
LD50	Lethal dose to kill 50% of test animals/organisms.
LEL	Lower explosive level.
OSHA	American Occupational Safety and Health Administration.
TEL	Tolerable Exposure Limit.
TLV	Threshold Limit Value-an exposure limit set by responsible
	authority.
UEL	Upper Explosive Level
WES	Workplace Exposure Limit
	•

- 1. HSNO Approved Code of Practice: Preparation of Safety Data Sheets, September 2006.
- 2. Australia Approved Criteria for Classifying Hazardous Substances -[NOHSC:1008(2004)]
- 3. Safework Australia: Preparation of SDS sheets for hazardous chemicals (Code of Practice).

Disclaimer

This document has been issued by TCC (NZ) Ltd and serves as their Safety Data Sheet ('SDS'). It is based on information concerning the product which has been provided to TCC (NZ) Ltd or obtained from third party sources and is believed to represent the current state of knowledge as to the appropriate safety and handling precautions for the product at the time of issue. Further clarification regarding any aspect of the product should be obtained directly from the manufacturer. While TCC (NZ) have taken all due care to include accurate and up-to-date information in this SDS, it does not provide any warranty as to accuracy or completeness. As far as lawfully possible, TCC (NZ) Ltd accept no liability for any loss, injury or damage (including consequential loss) which may be suffered or incurred by any person as a consequence of their reliance on the information contained in this SDS

The information herein is given in good faith, but no warranty, express or implied is made.

Please contact the Australian manufacturer, if further information is required.

Issue Date: 7 November 2016 Review Date: 7 November 2021